



Trevor Boundy <trevor@boundy39.com>

---

**FW: 4 Waco SRE - Fuselage Framing (Part 3)**

1 message

---

**Tandy Walker** <rdb435021@icloud.com>

Mon, Aug 10, 2020 at 10:19 PM

To: "Robert J. Galler" <meccanom@msn.com>, Trevor Boundy <jtboundy@dcsi.net.au>

---

**From:** Tandy Walker [mailto:[aerotan1503@outlook.com](mailto:aerotan1503@outlook.com)]

**Sent:** Saturday, March 22, 2014 3:07 PM

**To:** [aerotan1503@outlook.com](mailto:aerotan1503@outlook.com)


**Subject:** 4 Waco SRE - Fuselage Framing (Part 3)

Web Site: [tandysmodelplanes.com](http://tandysmodelplanes.com)

*Waco SRE*

*March 22, 2014*

Before removing the Section 2 side, 3/32" balsa fillets were glued into the two side windows as shown below.



The corner triangular pieces were then sanded into curved window fillets after the glue dried as shown below...Tandy

